Work Orde Friday, April 09,					1		*					Page 1
Revision ID:	D4021-5 Blanking Plate	e e		Accept				S	Setup	Start Stop	1 18811181 81	
	4/12/2010	Start Qty: 6.00 Req'd Qty: 6.00			Cust Item II Customer:	D:					1 12411(2)	
Approvals:		an: UMF	Date: 10 -4-9.	Tooling: SPC (Y/N):		te:	-	F	Run	Start Stop		
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Rey	vision Nbr					****					
D4021		Dep B								-		Ph=
100 Waterjet	,	Memo		0.00			,	(<u>B 10</u>	<u> </u>	- 12	u)
FLOW CNC Waterj		Prog Rev Dwg Rev	v: 									8
110		Deburr a QC2- Inspect parts of	s required	0.00								
QC Quality Control		Memo	it machine i Aut Aib	0.00					<u> </u>	<u>-H -</u> ((<u>)</u>	

w/o: 5	7612	perm change WORK ORDER C	HANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
iolulis	100	Heapon box should be @ New B.	A	Q, 40, M			S Iduilis

	Resolution:		Disposition:	QA: N/C Closed:	Date:
Part No:	D4021-5	_ PAR #:	Fault Category:	NCR: Yes No DQA:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC	Corrective Action Section B		Verification	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
	·							-			
			·				`				
								ļ			

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID 57612 Friday, April 09, 2010 2:45:57 PM

Page 2

Item ID:

D4021-5

Accept

Setup Start



Revision ID:

Item Name:

Blanking Plate

Start Date: Required Date: 4/13/2010

4/12/2010

Start Oty: 6.00

Rea'd Oty: 6.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: Date:

QC: Date:

Tooling:

SPC (Y/N):

Date:

Run

Start

Stop



Stop

Sequence ID/

Work Center ID

120

Ouality Control

Operation Description

OC8- Inspect parts - second check

Set Up/ Run Hours

Draw Number

Date:

Draw Plan Rev. Code

Accept Qty

Reject Oty

Reject Number Stamp

Insp.

Memo

140

Packaging

Packaging

Memo

0.00

0.00

150

Quality Control

OC21- Final Inspection - Work Order Release

Identify as per dwg & Stock Location:

0.00

Memo

0.00

W/0:5	1612	WORK ORDER CHANGE	ORDER CHANGES						
DATE	STEP	Perm. change Due to New B" Day.	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
iobilos	世	- Pander cont per as 2005 white MIHZO 7 Start time 11:00Ah	y	rolodia	8		S colorelis		
	122	OL3 conspect Pouclu contry	BP	10-nl-19	8	(2014/15		

Part No: $\underline{\mathcal{D}}$	1021-5	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
	T	Description of NC		Corrective Action Section B		Verification	Approval	Approval QC Inspector			
DATE	STEP	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng				
								-			
								}			
				100000							
· va-		· · · · · · · · · · · · · · · · · · ·									
								}			

NOTE: Date & initial all entries

Picklist Print

Friday, April 09, 2010 2:45:56 PM

Work Order ID: 57612

Parent Item:

D4021-5

Parent Item Name:

Blanking Plate

Comments:

IPP RevA: new issue DD 09.11.25 verified by:EC

REV.A DD 10.02.22 verified by:EC

IPP Rev:B as per dwg

Start Date: 4/12/2010

Required Date: 4/13/2010

Start Qty: 6.00

Required Qty: 6.00

Component Item ID/ Item Name

M304S16GA

Replacement Mfg/ Item ID

Purch Purchased

Bin Primary Item Location No

Last Location

Route Seq ID 100

Unit of Measure sf

Qty on Remaining Hand 0.3928 17.1000

Qty Qty To Pick Issued Date Issued

Status

Page 1

1310-4-12

1 (85) \$501 (85 10) (850) 650 (81 10) (10) 8(0) (850) (81 10)

304/316 Sheet .063	

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
MAT20	17.1		<u> </u>
113295	17.1		113795

W/O:			WC	RK ORDER CHANG	ES						
DATE STEP		PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								, 100 mg.			
			· - · · · · · · · · · · · · · · · · · · ·								
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A :	Date:			
							sed: Date:				
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCF	R)					
DATE	STEP	Description of NC				Verific	fication Approval		Approval		
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Sect	ion C	Chief Eng	QC Inspector		
									-		
··											

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order: S76(う
Description: BLANKING PLATE	Part Number: D ЦОЭ1-5
Inspection Dwg: 0401-4, Rev: # B	Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

		I II SE ALLI			-71	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
ф .194	1.005001	.196	1			
3.50	i .	3,507	29-			
02.G		2.563	٧			
18.	4.00	1815	8			
, 060	61	,658	8			
				1		
	·					
	·					
-	· · · · · · · · · · · · · · · · · · ·					
			 			
				1		
Measured by:	B	Audited by:	States	P	rototype Appro	val:
Date:	 	Date:	10/04/15		D	ate: //
5410.	10.7-12		1010 411 3	ل		

						
Measured by:	ıR	Audited by:	diate:	Prototype Approval:		L
Date:	(0-4-17	Date:	14/44/15	Date:	/	B
	(0.1(1)		1010 111 3			

Г	Rev	Date	Change	Revised by	Approved
-	Α		New Issue	 KJ/JLM	



	•								
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHAI	EDURE CHANGE		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		· · · · · · · · · · · · · · · · · · ·							
Part No	i	PAR #:	Fault Categ	jory:	_ NCR: Yes	No DQ	A:	Date: _	
		olution:							
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	1)		<u>, , , , , , , , , , , , , , , , , , , </u>	
DATE	STEP	Description of NC	Corrective Action Section B		<u> </u>	Verification		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector
									-

· NOTE: Date & initial all entries